
BR Servicii de reparatie auto FORD ECOSPORT

I.D.: 68655365

Data publicarii	28.04.22	Coduri CPV	50112100-4 50112000-3
-----------------	----------	------------	-----------------------

Pretul estimativ:	954,34 RON - 954,34 RON
-------------------	-------------------------

Descriere:	Reparatie instalatie electrica, inlocuire set placute frana fata, inlocuire bielele bara stabilizatoare spate.
------------	--
