



**Pachet REPARATIE pompa V1337-T72 Ex + Flansa autocuplaj
KK80+Set garnitura autocuplaj Homa DN80**

I.D.: 61541079

Data publicarii	30.09.21	Coduri CPV	50511100-1 50511000-0
-----------------	----------	------------	-----------------------

Pretul estimativ:	10.636,21 RON - 10.636,21 RON
-------------------	-------------------------------

Descriere: Etansarile mecanice s-au deteriorat excesiv, motiv pentru apa a patruns in ulei, apoi in motor, care s-a ars. Reparatia pompei cuprinde urmatoarele piese de schimb: - Rulment-2buc; - Etansare mecanica - 4 buc; - Rulment -2 buc; - Kit O-RING-uri - 2buc; - Ulei - 1litri; Reparatia pompei presupune urmatoarele servicii: - Rebobinare motor; - Demontare/montare/testare. Set garnitura autocuplaj Homa DN80 -material EPDM; - diametru DN 80; ***Setul contine 6bucati. Flansa autocuplaj KK80.
