
Reparatie si verificare UTAS UM-300-15-S,SN:M715.21S03.0244, SN:M715.21S03.0248, SN:M.715.21S03.0008

I.D.: 103748053

Data publicarii	03.10.24	Coduri CPV	50421000-2
-----------------	----------	------------	------------

Pretul estimativ: 840,00 RON - 840,00 RON

Descriere: **Reparatie si verificare UTAS UM-300-15-S,SN:M715.21S03.0244, SN:M715.21S03.0248, SN:M.715.21S03.0008** Descriere: 1. **Reparatie UTAS UM-300-15-S, sn:M715.21S03.0244 - Verificare functionare cu generatorul NIBP, SPO2, ECG x 2 = 400,00 (RON) - Resoftare aparat, remdiere contact imperfect la modulul NIBP, Verificare functionare cu generatorul NIBP, SPO2, ECG.** 2. **SN:M715.21S03.0248 - Verificare functionare cu generatorul NIBP, SPO2, ECG. x 1 = 220,00 (RON)** 3. **SN:M.715.21S03.0008 - Verificare functionare cu generatorul NIBP, SPO2, ECG. x 1 = 220,00 (RON)**
