

---

## **ADV1158692 - REPARATIE CONTROLLER Leica CS10**

I.D.: 48690334

---

Data publicarii	04.08.20	Coduri CPV	50700000-2 50410000-2
-----------------	----------	------------	-----------------------

---

Pretul estimativ: 4.575,00 RON - 4.575,00 RON

---

Descriere: Reparatie controller tip CS10 (inlocuire afisaj touchscreen - producator Leica Geosystems) - 1 buc, pret unitar 1225.00 Lei Manopera efectuare operatiuni de service - 300 Lei. Garantia 1 an pentru piesele inlocuite. Termen de prestare: 30 de zile de la data comenzii.

---