
Servicii de reparare iSOLO 500L

I.D.: 71735514

Data publicarii	29.07.22	Coduri CPV	50411000-9
-----------------	----------	------------	------------

Pretul estimativ:	30.000,00 RON - 30.000,00 RON
-------------------	-------------------------------

Descriere:	Servicii de reparare iSOLO 500L, inclusiv inlocuirea detectorului defect (CAM2000-500AM PIPS Detector)
------------	--
