
Inspectie de service Skoda RAPID

I.D.: 101811509

Data publicarii	21.08.24	Coduri CPV	50112200-5
-----------------	----------	------------	------------

Pretul estimativ: 675,38 RON - 675,38 RON

Descriere: Inspectie de service Skoda RAPID fara schimb ulei, cu inlocuit lichid frana, inlocuit filtru aer, conform oferta: Manopera: 360,00 RON Materiale: 315,38 RON
