
Servicii de reparare si intretinere (Rev.2)

I.D.: 39768136

Data publicarii	17.05.18	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ:	180,67 RON - 180,67 RON
-------------------	-------------------------

Descriere:	serviciu de reparare si intretinere vw transporter inlocuit placute frina spate
------------	---
