
Reparatie buldoexcavator Komatsu WB 93S-5 F20288

I.D.: 44015143

Data publicarii 17.09.19

Coduri CPV

50110000-9

Pretul estimativ: 5.634,58 RON - 5.634,58 RON

Descriere: Reparatie pompa de injectie si pompa de alimentare la buldoexcavator Komatsu WB 93S-5 F20288
