
reparat pompa WILO 1.5KW/3000T

I.D.: 53718383

Data publicarii	27.01.21	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ:	1.900,00 RON - 1.900,00 RON
-------------------	-----------------------------

Descriere:	demontat montat, rebobinat stator, inlocuit etansare mecanica 2 buc. inlocuit rulmenti SKF, inlocuit ulei, reparat cablu
------------	--
