
Servicii de reparare si intretinere auto Hyundai Tucson NT 28 API

I.D.: 57332863

| | | | |
|-----------------|----------|------------|------------|
| Data publicarii | 26.05.21 | Coduri CPV | 50112000-3 |
|-----------------|----------|------------|------------|

Pretul estimativ: 403,37 RON - 403,37 RON

Descriere: servicii de reparare si intretinere auto Hyundai Tucson NT 28 API cf.Deviz de reparatii nr.4907/20.05.2021:placute frana fata = 134.45 lei placute frana spate = 100.84 lei manopera inlocuit set placute frana fata+spate = 4h x 42.02 lei(ora) =168.08 lei
