
Servicii de reparare VW TRANSPORTER

I.D.: 98000188

Data publicarii	28.05.24	Coduri CPV	50112100-4
-----------------	----------	------------	------------

Pretul estimativ: 3.592,16 RON - 3.592,16 RON

Descriere: Servicii de reparare autovehicul VW TRANSPORTER ce includ: inlocuire rulment roata,senzor,disc frana spate,set placute frana spate,degripare senzor Nox,diagnoza monitorizare VAS5051,materiale mici,verificat eficacitate franare.
