
Reparatie VW T5 Kombi

I.D.: 71567697

Data publicarii	20.07.22	Coduri CPV	50112100-4
-----------------	----------	------------	------------

Pretul estimativ: 856,27 RON - 856,27 RON

Descriere: Inspectie service fara schimb ulei Filtru motorina - demontat/inlocuit /montat Service lichid frana - efectuat Sistem ambreiaj - aerisit Eficacitate franare - verificat
