
Schimb roti si reparatii Skoda Rapid

I.D.: 89847084

Data publicarii	21.11.23	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ:	541,53 RON - 541,53 RON
-------------------	-------------------------

Descriere:	Inlocuire set roti vara cu set roti iarna Echilibrat roti Efectuare diagnoza Furtun vacuum demontat / inlocuit / montat
------------	---
