

---

## Reparatie Mercedes-Benz Sprinter

I.D.: 28755555

---

Data publicarii	08.06.18	Coduri CPV	50110000-9
-----------------	----------	------------	------------

---

Termenul limita pentru depunere:	11.06.18	Pretul estimativ:	1.504,00 RON
----------------------------------	----------	-------------------	--------------

---

Descriere: Reparatie Mercedes-Benz Sprinter, an de fabricatie 2008, nr. de identificare WDB9066331S276991, care prezinta defectiuni la alternator, cureaua de transmisie si role, sistemul de aer conditionat si senzor de presiune rampa combustibil.

---