

Reparatie ceas electronic tripla fata

I.D.: 37720408

Data publicarii	06.08.19	Coduri CPV	50431000-5
-----------------	----------	------------	------------

Pretul estimativ: 11.404,00 RON - 11.404,00 RON

Descriere: Demontare, transport, montare, inlocuire 166 buc. clustere leduri arse, inlocuire unitate comanda, inlocuire senzor temperatura, inlocuire stipler doua fete, sistem racire forata doua fete.
