
Service stingatoare si hidranti interiori

I.D.: 43269254

Data publicarii	26.02.20	Coduri CPV	50413200-5
-----------------	----------	------------	------------

Pretul estimativ: 1.712,40 RON - 1.712,40 RON

Descriere: Service hidrant interior: 40 buc x 35 lei Verificat stingator tip P6: 12 buc x 9.2 lei Verificat stingator tip P50: 1 buc x 40 lei Verificat stingator tip G2: 18 buc x 9 lei
