

---

## Interventie service la HPLC 1200

I.D.: 19589126

---

Data publicarii	09.05.17	Coduri CPV	50410000-2
-----------------	----------	------------	------------

---

Termenul limita pentru depunere:	11.05.17	Pretul estimativ:	4.700,00 RON
----------------------------------	----------	-------------------	--------------

---

Descriere: Interventie service la HPLC 1200 necesita înlocuirea urmatoarelor componente: 1. 25466 restek frits, ptfe, 5pk, cantitatea- 2 buc.; 2. 25276 restek outlet ball valve, cantitatea- 1 buc.; 3. 26393 restek active inlet cartridge designed, cantitatea- 1 buc.; 5. 22482 restek pump block piston seal, ptfe w/graphite 2pk, cantitatea- 1 buc.; 6. 25265 restek needle seat assembly , cantitatea- 1 buc.; 7. B-G1311-81601 capillary, outlet valve to damper, cantitatea- 1 buc.; 8. Manopera reparatie, calibrare si punere in functiune.

---