
Reparatii la HYUNDAI SANTA FE BH12WAT

I.D.: 43366910

Data publicarii	25.06.19	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ:	533,33 RON - 533,33 RON
-------------------	-------------------------

Descriere:	Inlocuit pompa de ambreaj si aerisire la Hyundai Santa Fe BH12WAT
------------	---
