
Servicii de reparare si intretinere.

I.D.: 45773691

Data publicarii	22.04.20	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ: 589,05 RON - 589,05 RON

Descriere: Oferta refuzata: Reparatie autoturism DACIA DUSTER nr. inmatriculare CS07KSE din parcul auto al OCPI Caras-Severin, conform Ofertei nr. 274/21.04.2020 - Inlocuire butuc roata cu rulment - 126,05 RON/ora - Butuc roata - 120 RON/buc - Prezon roata - 25 RON/buc - Rulment roata cu abs - 200 RON/buc
