
Reparatie UPS APC 10 000 VA

I.D.: 59879801

Data publicarii 11.08.21

Coduri CPV

50323200-7

Pretul estimativ: 3.180,00 RON - 3.180,00 RON

Descriere: Reparatie UPS APC 10 000 VA reconditionat placa control;inlocuit baterie acumulatori
