
Reparatie Hyundai Tucson

I.D.: 62033061

Data publicarii	15.10.21	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ:	6.214,05 RON - 6.214,05 RON
-------------------	-----------------------------

Descriere: Reparatie Hyundai Tucson DISC-PLACA AMBREIAJ,CILINDRU AMBREIAJ, PAD KIT-FRONT DISC BRAKE,BIELETA BS FATA,VERIFICARE MECANICA RAMPA,INLOCUIT KIT AMBREIAJ, INLOCUIT RULMENT PRESIUNE,INLOCUIT BIELETE A/R FATA,PRELUCRARI MECANICE,REPARATIE TINICHIGERIE
