

REPARATII IMPRIMANTA HP 1015 si REPARATIE APARAT NUMARAT MONEZI

I.D.: 43717909

Data publicarii 14.08.19 Coduri CPV 50000000-5 50323000-5

Pretul estimativ: 544,01 RON - 544,01 RON

Descriere: SERVICE IMPRIMANTA, REPARATIE CUPTOR, SCHIMBARE UPPER FUSER SI LOWER FUSER UNIT si SERVICE APART NUMARAT MONEZI, SCHIMBARE CURELE DE TRANSMISIE
