
SERVICII DE REPARATIE SI INTRETINERE AUTO

I.D.: 66851030

Data publicarii	04.03.22	Coduri CPV	50100000-6
-----------------	----------	------------	------------

Pretul estimativ:	1.445,38 RON - 1.445,38 RON
-------------------	-----------------------------

Descriere: inlocuit senzori ABS fata, inlocuit intrerupator stop frana, inlocuit releu bujii, inlocuit bujii incandescente, verificat si reglat cu tester electronic, la auto marca Logan, nr. AG 10 ZNH
