
Servicii de reparare masina de spalat ind. Electrolux

I.D.: 76278277

Data publicarii	09.12.22	Coduri CPV	50532000-3
-----------------	----------	------------	------------

Pretul estimativ: 1.152,00 RON - 1.152,00 RON

Descriere: Reparatie masina de spalat rufe industriala Electrolux 35 kg , inlocuit sensor de temperatura ,inlocuit electrovalva apa la DGASPC SECTOR 1 / CSS. ODAI
