

---

## Servicii de reparatie Mercedes Benz Sprinter MAI 34240

I.D.: 92810315

---

Data publicarii 29.01.24

Coduri CPV

50112000-3

---

Pretul  
estimativ: 4.958,92 RON - 4.958,92 RON

---

Descriere: Servicii de reparatie Mercedes Benz Sprinter MAI 34240 - Inlocuit Volanta Set ambreiaj  
Lichid racire

---