

SERVICII DE REPARARE SI DE INTRETINERE A FOTOCOPIATOARELOR

I.D.: 44641836

Data publicarii 22.11.19 Coduri CPV 50313200-4

Pretul estimativ: 2.482,90 RON - 2.482,90 RON

Descriere: 1.HP 1022 SEPARATION PAD ASSEMBLY (RM1-2048-000) HP 3050/3055/3052/M1319F BC 1 2
TONER REFILL HP2000/4000/CANEP27 BC 6 3 RL1-0266 ROLLER PICK UP LBP-1080 BC 1 4
SAMSUNG ML- 1660 ML-1910 ML-1610 ML-3310 TONER REFILL (70GR) BC 5 5 RES.CHIP XEROX
2778ME BC 3 6 RESET CHIP SAMS 111S BC 4 7 RES.CHIP LEXMARK MX310 (4.5K) BC 1 8 TONER
HP LJ 1010/1012/1015/1020/1022/3015/3020 140G BC 5 9 TONER
SAMSUNGML1010/1020/1210/1710/17 (140gr) BC 3 10 XEROX 3330/WC3335 (15K) PFF CHIP
BC 1 11 DLC SAMSUNG MLT- D101S(ML2160/SCX3400) 1.5K BC 1 12 XEROX
WC3215/P3260(3K) LASERCARTRIDGE(106R02778) BC 1 13 HP Q2612A/FX10 LASER
CARTRIDGE BC 1 14 BROTHER HL-2240,HL-2130 TN2210,TN2220,TN2010 TONER REFILL SCC
BC 1 15 XEROX 3330 8.5K LASER CARTRIDGE BC 1 16 XEROX PHASER 3330(3335) CHIP
(8.5K/15K) BC 1 17 RESET CHIP SAMSUNG 116S BC 2 18 HP LASERJET 1010 1160 1100 1200
1320P2015 LAMELA STERGERE UNIVERSALA BC 1 19 TONER SAMSUNG ML
1010/1020/1210/1710(80gr) BC 3 20 CZ102AE HP INK CARTUS IMPRIMANTA NR.650 COLOR BC
1 21 CURATIRE CART BROTHER BC 1 22 DLC HP CF283X/CRG737 2.4K BC 1 23 WIPER BLADE
SAMS. MLT-D101/D111 FOR OEM BC 1