
Servicii de reparatie marmita

I.D.: 75724860

Data publicarii	24.11.22	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ:	303,03 RON - 303,03 RON
-------------------	-------------------------

Descriere:	Servicii de reparatie marmita - inlocuire termocupla 1 buc
------------	------------------------------------------------------------
