
Servicii de reparatie hidranti de incendiu

I.D.: 52414542

Data publicarii	08.12.20	Coduri CPV	50413200-5
-----------------	----------	------------	------------

Pretul estimativ: 6.860,00 RON - 6.860,00 RON

Descriere: Servicii de reparatie hidranti de incendiu - montaj Teava refulare tip TURAP C52 D13, SUPRON 3, certificata CE , EN 671-2-10 buc - montaj Rola furtun tip C cu racorduri legate si manson 20 ml-6 buc - montaj Robinet hidrant 2" tip C fara racord fix-6 buc Aplicare masuri corective unghi usa cutie hidrant-6 buc Manopera montaj-1 buc
