
REPARATII POMPE SUMERSIBILE

I.D.: 69074669

Data publicarii	10.05.22	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ: 3.710,00 RON - 3.710,00 RON

Descriere: REPARATII AGITATOR FLYGT 1.5 KW :rebobinat ; inlocuire rulmenti;inlocuire presutupe ; ulei
REPARATII MIXER FAGGIOLATI : rebobinat ;lucrari mecanice conexe ; inlocuire
rulmenti;presutupa ; ulei
