



Servicii de reparatii motor ventilator la camera pompelor (rebobinat, inlocuit rulment si inlocuit condensator)

I.D.: 23518890

Documente participare:

ANUNT DE INTENTIE_REBOBINARE_MOTOR_VENTILATOR_CAMERA_POMPELOR_BAZIN_PLOMPIC_INLOCUIT_RULMENT_CAMERA_289.docx

Data publicarii	27.10.17	Coduri CPV	50532100-4
-----------------	----------	------------	------------

Termenul limita pentru depunere:	01.11.17	Pretul estimativ:	255,00 RON
----------------------------------	----------	-------------------	------------

Descriere:	Servicii de reparatii motor ventilator la camera pompelor (rebobinat, inlocuit rulment si inlocuit condensator)
------------	---
