
Piese de schimb reparatie echipament medical

I.D.: 105958031

Data publicarii	21.11.24	Coduri CPV	34913000-0 50421000-2
-----------------	----------	------------	-----------------------

Pretul estimativ:	2.610,00 RON - 2.610,00 RON
-------------------	-----------------------------

Descriere: Piese de schimb placa de comanda si control ECTF pentru echipamente Fiocchetti (reparatie) - 1350 lei - Motor ventilator condensor Fiocchetti (schimbare piesa). 1260 lei
