
Serviciu de reparatie Dacia Duster

I.D.: 83572689

| | | | |
|-----------------|----------|------------|------------|
| Data publicarii | 14.06.23 | Coduri CPV | 50112000-3 |
|-----------------|----------|------------|------------|

| | |
|-------------------|-----------------------------|
| Pretul estimativ: | 1.359,25 RON - 1.359,25 RON |
|-------------------|-----------------------------|

Descriere: Serviciu de reparatie Dacia Duster inlocuit rezistenta ecetroventilator racier motor inlocuit electroventilator inlocuit commutator coloanal directie
