

---

## **PACHET REPARATIE APARATURA BTL**

I.D.: 56033876

---

Data publicarii	13.04.21	Coduri CPV	34913000-0
-----------------	----------	------------	------------

---

Pretul estimativ: 3.180,00 RON - 3.180,00 RON

---

Descriere: BTL-5820SL seria 5001-0382032 a) 3 x buton encoder ( 2 x intensitate ; 1 x select ) - 3 x 100.00 Ron fara TVA = 300.00 RON fara TVA b) Cablu sonda cluster - 490.00 RON fara TVA c) Ventilator sonda cluster - 490.00 RON fara TVA d) Carcasa sonda cluster - 490.00 RON fara TVA e) Carcasa sonda ultrasunet - 490.00 RON fara TVA f) Pastila vibratoare sonda ultrasunet - 490.00 RON fara TVA g) 4 x electrod 5/7 cm - 4 x 70.00 Ron fara TVA = 280.00 RON fara TVA h) 2 x cablu electro gri / alb - 2 x 55.00 RON fara TVA = 110.00 RON fara TVA i) 4 x burete 5/7 cm - 4 x 10.00 RON fara TVA = 40.00 RON fara TVA

---