
Reparatie auto Ford EcoSport

I.D.: 90399759

Data publicarii	29.11.23	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ:	13.320,99 RON - 13.320,99 RON
-------------------	-------------------------------

Descriere:	Inlocuire distributie, turbina, pompa ulei, filtru ulei si ulei. Lucrarea include manopera si piesele aferente.
------------	---
