
Servicii de reparatie la autoturism Dacia Logan Van -12179

I.D.: 48117527

Data publicarii	14.07.20	Coduri CPV	50100000-6
-----------------	----------	------------	------------

Pretul estimativ: 689,01 RON - 689,01 RON

Descriere: Servicii de reparatie la autoturism Dacia Logan Van -12179: include inlocuit senzor detector apa in combustibil si diagnosticare tester Clip. Lucrarea se efectueaza cu pieseschimb origine Dacia
