

## Servicii de reparare si manopera a autoturismului VW Touareg

I.D.: 42704363

---

Data publicarii	09.05.19	Coduri CPV	50110000-9
-----------------	----------	------------	------------

---

Pretul estimativ:	16.642,84 RON - 16.642,84 RON
-------------------	-------------------------------

---

Descriere: in vederea functionarii la parametri normali se doreste inlocuirea urmatoarelor:Set placate frana fata -1 buc.,Set placate frana spate -1 buc,Senzor uzura placate frana spate -2 buc,Senzor uzura placate frana fata -2 buc Filtru ulei -1 buc,Filtru polen -1 buc,Filtru combustibil -1 buc,Filtru aer -1 buc,Surub evacuare -1 buc,Ulei motor Castrol EDGE LONGLIFE III 5W/30 -9 Lit.,Spray curatat -11 buc,Lant distributie dr. -1 buc,Patina lant -1 buc Patina lant ghidare -1 buc,Patina lant -1 buc,Patina lant -1buc,Intinzator lant -1 buc,Lant distributie STG -1buc,Patina lant distributie -1 buc,Patina intinzatoare -1 buc,Simering palier -1buc,Lager - 2buc,Garnitura capac culbutori - 1 buc,Garnitura capac culbutori - 1 buc,OE VW/Surub - 6 buc,Element injector - 6 buc,Garnitura capac distributie - 1 buc,O-ring conducte- 4 buc,Garnitura capac distributie - 1 buc,Capac VW-1 buc,Tachet hidraulic OE- 10 buc Rola ghidare curea transmisie - 1 buc,Lagar inel alunecare- 1 buc,Rola ghidare - 1 buc,Rulment alternator - 1 buc,Rulment alternator - 1 buc,Fulie alternator- 1 buc,Rola ghidare curea transmisie - 1 buc,Curea transmisie - 1 buc Turbosuflanta - 1 buc,Garnitura intre turbo si bloc - 1 buc,Simering LA CV - 1 buc,Garnitura intre turbo si suport - 1 buc,Vas spalator parbriz cu pompa OE - 1 BUC,Ulei servo - 2 buc,Amortizor axa spate - 2 buc,Senzor temperatura - 1 buc

---