
revizie Toyota Hilux CL 04 BKO

I.D.: 40474077

Data publicarii	03.12.19	Coduri CPV	50112100-4 50110000-9
-----------------	----------	------------	-----------------------

Pretul estimativ: 4.276,31 RON - 4.276,31 RON

Descriere: CUREA DISTRIBUTIE:220.09 ROLA CUREA DISTRIBUTIE:344.33 AX INTINZATOR CUREA:61.73 SAIBA INTINZATOR:12.60 INTINZATOR DISTRIBUTIE:491.30 SURUB DISTRIBUTIE:8.74 MATERIALE AUXILIARE:48 MANOPERA KIT DISTRIBUTIE:540 ULEI MOTOR:310.87 SAIBA BUSON ULEI:6.27 FILTRU ULEI:55.85 FILTRU AER:197.81 FILTRU COMBUSTIBIL:120.61 FILTRU POLEN:160.63 SPRAY CLIMATIZARE:61.91 ANTIGEL:487.10 LICHID FRANA:69.94 ULEI CUTIE VITEZA:183.09 SAIBA BUSON:10.5 ULEI DIFERENTIAL:228.09 SAIBA BUSON:4.52 SAIBA BUSON:5.83 SAIBA BUSON:10.50 MANOPERA:600 TEST FRANA:36
