

---

## Reparatie pompa de spalat cu presiune HD 5/15

I.D.: 69835581

---

Data publicarii 03.06.22

Coduri CPV

34913000-0

---

Pretul  
estimativ: 690,00 RON - 690,00 RON

---

Descriere: Reparatia contine: stecher-1buc; manopera-1h; sertizat-1buc; roata-1buc; furtun hoby-1buc;

---