

Servicii de reparare Hyundai Tucson cu nr. de inmatriculare CT24API apartinand A.P.I.A.Constanta

I.D.: 42882798

Data publicarii	30.05.19	Coduri CPV	50110000-9
-----------------	----------	------------	------------

Pretul estimativ: 15.987,41 RON - 15.987,41 RON

Descriere: Servicii de reparatii constând in: -alezat,honuit bloc motor la cota marita -bucsat biela -dezechipat echipat chiulasa -dezechipat echipat motor la banc -verificat fisuri chiulasa -D/R grup motopropulsor -planat bloc motor -rectificat arbore cotit -rectificat planeitate chiulasa -inlocuit turbocompresor Inlocuit: -adeziv universal 1 buc -filtru ulei 1 buc -cuzineti biela 1 buc -cuzineti palier 1 buc -ulei Castrol 5W30 5L 1 buc -kit distributie 1 buc -levier 8 buc -piston 4 buc -pompa apa 1 buc -racitor ulei 1 buc -set garnituri motor 1 buc -set simering supape 1 buc -set surub chiulasa 1 buc -ulei atf 1 buc -antigel G12 4 buc -bucsa biela 4 buc -apa distilata 4 buc surub biela 8 buc -supapa admisie 8 buc -supapa evacuare 8 buc -simering ax came 1 buc -solutie degresare 6 buc -culbutor admisie scurt 4 buc -pompa ulei 1 buc -garnitura chiulasa 1 buc -turbocompresor 1 buc -culbutor evacuare lung 4 buc .Total manopera 4431,00 ron Total piese 11556,41 ron .
