
REPARATII AUTO

I.D.: 76230917

Data publicarii	05.12.22	Coduri CPV	50112100-4
-----------------	----------	------------	------------

Pretul estimativ: 1.689,52 RON - 1.689,52 RON

Descriere: 1.Reparatii auto Dacia Duster PH 47 PCP - Inlocuit bucsi bara stabilizatoare fata, inlocuit termostat, inlocuit lichid racire, inlocuit discuri si placate frana fata, inlocuit conducta apa, test rane, reglat geometrie roti - 1370,54 lei 2. Reparatii auto Skoda Fabia PH 03 PCP - Inlocuit bujii - 318,98 lei
