

---

## Reparatie OTOKAR TERRITO A-10719

I.D.: 102351918

---

Data publicarii	04.09.24	Coduri CPV	50112000-3
-----------------	----------	------------	------------

---

Pretul estimativ: 4.517,60 RON - 4.517,60 RON

---

Descriere: Conditii neacceptate la termen: Serrviciu reparatie OTOKAR TERRITO cu nr de inmatriculare A10719: inlocuire claxon, buton cablu capota roata rezerva, inlocuire stergator, cablu capota roata rezerva si kit reparatie etrier spate.

---