
Pachet reparatie tractor

I.D.: 59853802

| | | | |
|-----------------|----------|------------|------------|
| Data publicarii | 10.08.21 | Coduri CPV | 16810000-6 |
|-----------------|----------|------------|------------|

Pretul estimativ: 1.048,19 RON - 1.048,19 RON

Descriere: 1 21-D1/15/40/20 Rosneft Revolux D1 15w-40 (20 L.)(21-D1/15/40/20) buc 3.00 183.38 2
RP70-050 Supapa de siguranta RP-70 (Belarus)(RP70-050) buc 1.00 208.13 3 75-007-01
Supapa de suprapresiune R-80(75-007-01) buc 1.00 33.61 4 FT65.48.055 Releu de viraj
FT754(FT65.48.055) buc 1.00 16.81 5 FT700.37.128 Furcă c/v FT704*754(FT700.37.128)
buc 1.00 42.02 6 820-4635022 Arcul s/s MTZ-1221(820-4635022) buc 1.00 25.21 7
3912.3769-03 Întrerupător semnal de viraj MTZ (cu cabluri)(3912.3769-03)buc 1.00 92.44 8
738.3747-30 Releu de conducere demaror 12V MTZ tip nou(738.3747-30) buc 1.00 12.61 9
UR-2 Regulator de tensiune MTZ (7901.3702 G3) 14V 5A(UR-2) buc 2.00 33.61
