
Rep.auto la Dacia Duster

I.D.: 102382563

Data publicarii	02.09.24	Coduri CPV	50100000-6 50110000-9
-----------------	----------	------------	-----------------------

Pretul estimativ:	885,25 RON - 885,25 RON
-------------------	-------------------------

Descriere: Reparatii la auto Dacia Duster MAI 47033 (manopera+piese) : inlocuire conducta aer intre turbocompresor si schimbator; test calculator
