
Reparatie autoclav AES28 RAYPA (Lab.)

I.D.: 61691520

Data publicarii	05.10.21	Coduri CPV	50400000-9 50000000-5
-----------------	----------	------------	-----------------------

Pretul estimativ:	3.177,00 RON - 3.177,00 RON
-------------------	-----------------------------

Descriere: Reparatie autoclav AES28 RAYPA prin inlocuirea pieselor: Termostat de siguranta cost:621
Rezistenta cost 1099lei Verificare valva de siguranta cost 232 lei si manopera aferenta
montajului acestor piese: 175Lei/h, cost :1225
