
Reparatie mixer SRP 50.30.684.25, motor 5.7 kW

I.D.: 42799818

Data publicarii	14.05.19	Coduri CPV	50511100-1
-----------------	----------	------------	------------

Pretul estimativ:	2.562,00 RON - 2.562,00 RON
-------------------	-----------------------------

Descriere:	Reparatia consta in: - bobinare motor; - inlocuire rulmenti, etansari mecanice, simeringuri, O-ring-uri, ulei; - montaj; - probe.
------------	---
