
reparati imprimanta

I.D.: 68590256

Data publicarii	26.04.22	Coduri CPV	50323000-5
-----------------	----------	------------	------------

Pretul estimativ: 1.050,51 RON - 1.050,51 RON

Descriere: REPARATII IMPRIMANTA SAMSUNG XPRESS M2675F / RECONDITIONARE / RESETARE DRUM UNIT SERVICE / REPARATII MULTIFUNCTIONAL RICOH 1515 - 290.00 SCHIMBARE DRUM UNIT RICOH 1515 - 512.61 SCHIMBARE UPPER FUSER ROLLER - 113.45 SCHIMBARE PICK-UP ROLLER - 67.22
