
Reparare imprimanta Brother

I.D.: 52957634

Data publicarii	23.12.20	Coduri CPV	50313100-3 50300000-8
-----------------	----------	------------	-----------------------

Pretul estimativ: 300,00 RON - 300,00 RON

Descriere: Reparare modul USB imprimanta Brother HL- L5000 - Diagnoza, reparare placa de baza - lipire modul USB, verificare, punere in functiune - Modul USB on board SOCIETATE NEPLATITOARE DE TVA SOCIETATE NEPLATITOARE DE TVA
