
Servicii de reparare a fotocopiatoarelor

I.D.: 69821698

| | | | |
|-----------------|----------|------------|------------|
| Data publicarii | 31.05.22 | Coduri CPV | 50313100-3 |
|-----------------|----------|------------|------------|

Pretul estimativ: 550,00 RON - 550,00 RON

Descriere: WC 333x LAN/USB; -inlocuire rola fixing-fuser A4 cap. 50K pag - 1 buc; - inlocuire rola presoare teflon - 1 buc; - inlocuire termistor si senzor spraincalzire - 1 buc; -manopera aferenta curatare elemente optice si de transfer - 2 ore
