
Reparatie auto Mercedes Sprinter Trituro

I.D.: 75970009

Data publicarii	28.11.22	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ: 2.640,20 RON - 2.640,20 RON

Descriere: Baterie pornire - 1bc x 368 = 368 RON Regulator Turbina - 1bc x 343 = 343RON Ulei cutie viteve - 6l x89.2 = 355.2RON Deblocat culisori roata Stg/Dr - 2h x 150 = 300RON Set reparatii etrier - 2bc x 65 = 130RON Inlocuit lichid frana - 1.2h x 150 = 180RON Lichid frana - 2l x 32 = 64RON Reparat instalatie electrica - 2h x 300 = 600RON Diagnoza computerizata - 150 RON Manopera Regulator turbina - 1h x 150 = 150RON
