
Reparatie Suzuki Ignis

I.D.: 31807795

| | | | |
|-----------------|----------|------------|------------|
| Data publicarii | 05.11.18 | Coduri CPV | 50100000-6 |
|-----------------|----------|------------|------------|

| | | | |
|----------------------------------|----------|-------------------|------------|
| Termenul limita pentru depunere: | 06.11.18 | Pretul estimativ: | 750,00 RON |
|----------------------------------|----------|-------------------|------------|

Descriere: Reparatie autoturism Suzuki Ignis VL03ACV , seria : TSMMHY81S00179816, din 2004 ce consta in : inlocuire cabluri timonerie - schimbator - 2 buc, bucsi bara stabilizatoare fata - (4 buc) OE + manopera.
